



52512804 Repair Kit for a Gear

Kod produktu: 52512804



Kit consisting of 20 grooved pins (249620) and glue (683752), for repairing a Schindler gear for Varidor 10 door